



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 382210133
 CustomerID: INDS42
 CustomerPO:
 ProjectID:

Attn: **Elessar Connolly-Fairchild**
Indy Safety
5010 NE Roselawn St
Portland, OR 97218

Phone: (503) 501-7396
 Fax:
 Received: 12/12/2022 03:02 PM
 Analysis Date: 12/14/2022
 Collected: 12/5/2022

Project: **Banks School District-Middle School**

Banks School District-Middle School

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
521865 382210133-0001	Office Lobby	0.7	12/5/2022 5:20:00 PM	12/7/2022 5:39:00 PM	72	40	Customer
Sample Notes:							
507429 382210133-0002	Nurse Rm	0.4	12/5/2022 5:21:00 PM	12/7/2022 5:40:00 PM	73	40	Customer
Sample Notes:							
520279 382210133-0003	Vice P Rm	2.1	12/5/2022 5:22:00 PM	12/7/2022 5:41:00 PM	73	41	Customer
Sample Notes:							
520909 382210133-0004	Principal	0.5	12/5/2022 5:23:00 PM	12/7/2022 5:42:00 PM	73	40	Customer
Sample Notes:							
520196 382210133-0005	Isolation Rm	0.8	12/5/2022 5:24:00 PM	12/7/2022 5:43:00 PM	73	40	Customer
Sample Notes:							
520439 382210133-0006	Copier Rm	0.2	12/5/2022 5:27:00 PM	12/7/2022 5:44:00 PM	73	39	Customer
Sample Notes:							
521113 382210133-0007	Rm 109		12/5/2022 5:28:00 PM	12/7/2022	0	0	Customer
Sample Notes: Not Analyzed Radon device not received by lab.							
517566 382210133-0008	Rm 109 Office	0.7	12/5/2022 5:30:00 PM	12/7/2022 5:44:00 PM	73	38	Customer
Sample Notes:							
519770 382210133-0009	Rm 114	0.8	12/5/2022 5:32:00 PM	12/7/2022 5:46:00 PM	73	37	Customer
Sample Notes:							
517683 382210133-0010	Rm 115	0.8	12/5/2022 5:33:00 PM	12/7/2022 5:48:00 PM	74	37	Customer
Sample Notes:							



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order: 382210133

CustomerID: INDS42

CustomerPO:

ProjectID:

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
507637 382210133-0011	Rm 115	1.2	12/5/2022 5:33:00 PM	12/7/2022 5:48:00 PM	74	37	Duplicate
Sample Notes: Duplicate's Customer Sample:382210133-0010					Duplicate RPD = 40.0%		
520156 382210133-0012	Rm 116	0.3	12/5/2022 5:35:00 PM	12/7/2022 5:50:00 PM	74	36	Customer
Sample Notes:							
517716 382210133-0013	Rm 120	0.3	12/5/2022 5:37:00 PM	12/7/2022 5:51:00 PM	74	36	Customer
Sample Notes:							
520430 382210133-0014	Rm 121	0.4	12/5/2022 5:40:00 PM	12/7/2022 5:53:00 PM	74	37	Customer
Sample Notes:							
517908 382210133-0015	Counselor Office	0.5	12/5/2022 5:48:00 PM	12/7/2022 5:54:00 PM	74	37	Customer
Sample Notes:							
517647 382210133-0016	Staff Rm 130	0.5	12/5/2022 5:49:00 PM	12/7/2022 5:55:00 PM	74	40	Customer
Sample Notes:							
507502 382210133-0017	Library Rm 133 (1)		12/5/2022 5:50:00 PM	12/7/2022	0	0	Customer
Sample Notes: Not Analyzed Radon device not received by lab.							
519799 382210133-0018	Library Rm 133 (2)	0.6	12/5/2022 5:51:00 PM	12/7/2022 5:57:00 PM	74	37	Customer
Sample Notes:							
507494 382210133-0019	Library Office	0.2	12/5/2022 5:52:00 PM	12/7/2022 5:58:00 PM	74	37	Customer
Sample Notes:							
520573 382210133-0020	Music Rm 145- R	0.2	12/5/2022 5:58:00 PM	12/7/2022 6:00:00 PM	74	38	Customer
Sample Notes:							
521138 382210133-0021	Rm 145-F	0.3	12/5/2022 6:03:00 PM	12/7/2022 6:03:00 PM	75	37	Customer
Sample Notes:							
517839 382210133-0022	Rm 145-F	0.5	12/5/2022 6:03:00 PM	12/7/2022 6:03:00 PM	75	37	Duplicate
Sample Notes: Duplicate's Customer Sample:382210133-0021					Duplicate RPD = 50.0%		
517898 382210133-0023	Boys Locker	0.8	12/5/2022 6:09:00 PM	12/7/2022 6:14:00 PM	74	39	Customer
Sample Notes:							

Please visit www.radontestinglab.com



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order: 382210133

CustomerID: INDS42

CustomerPO:

ProjectID:

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
520412 382210133-0024	Girls PE Office	0.7	12/5/2022 6:19:00 PM	12/7/2022 6:19:00 PM	74	37	Customer
Sample Notes:							
520907 382210133-0025	Gym (1)-L	0.7	12/5/2022 6:25:00 PM	12/7/2022 6:25:00 PM	74	44	Customer
Sample Notes:							
514890 382210133-0026	Gym (2)-R	0.5	12/5/2022 6:26:00 PM	12/7/2022 6:27:00 PM	73	43	Customer
Sample Notes:							
507559 382210133-0027	Gym Office	0.7	12/5/2022 6:30:00 PM	12/7/2022 6:30:00 PM	73	42	Customer
Sample Notes:							
521060 382210133-0028	Cafeteria (1)	0.4	12/5/2022 6:31:00 PM	12/7/2022 6:32:00 PM	73	39	Customer
Sample Notes:							
507400 382210133-0029	Cafeteria (2)	0.4	12/5/2022 6:32:00 PM	12/7/2022 6:33:00 PM	74	41	Customer
Sample Notes:							
520138 382210133-0030	Blank	-0.1	12/5/2022 6:32:00 PM	12/7/2022 6:33:00 PM	74	41	Blank
Sample Notes:							
517712 382210133-0031	Blank	0.2	12/5/2022 6:32:00 PM	12/7/2022 6:33:00 PM	74	41	Blank
Sample Notes:							
507517 382210133-0032	Office 103	42	12/3/2022 8:33:00 AM	12/5/2022 8:33:00 AM	69.6	49.5	Customer
Sample Notes:							
507515 382210133-0033	Office 104	44.2	12/3/2022 8:33:00 AM	12/5/2022 8:33:00 AM	69.6	49.5	Customer
Sample Notes:							

Report Notes

Please visit www.radontestinglab.com



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order:	382210133
CustomerID:	INDS42
CustomerPO:	
ProjectID:	

Test Report: Radon in Air Test Results

Liquid Scintillation ID	Location	Radon Activity (pCi/L)	Start	Stop	Temperature F	Humidity %	Sample Type
-------------------------	----------	------------------------	-------	------	---------------	------------	-------------

The United States Environmental Protection Agency (EPA) has established a radon action level of 4.0pCi/L. EPA recommends mitigation of a structure if the confirmed radon level is equal to or greater than 4.0pCi/L.

The radon tests were performed using liquid scintillation radon detectors and counted on a liquid scintillation counter following EPA Method # 402-R-92-004 testing protocol for Radon in Air testing. EPA recommends retesting every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information.

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

Analyst(s)

Dominic Gehret (31)

Dominic Gehret, Radiochemistry Laboratory Manager, NJ Radon Measurement Specialist MES 13910 or other approved signatory

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ FL RB2034/R2687,IL RNL2008202,IN RTL00935,IA RNLAB10005,KS KS-LB-0005/KS-MS-0482,ME SPC202,MN RL-0005,NE 474/RMB-1083,NJ 03036/MEB92525/MES13910,NY 10872,OH RL39,OK D9952,PA 2573/3393/68-00367,RI RMB-108/RI00179,WV RL000220,NRSB-ARL6006,NRPP

Initial report from 12/15/2022 09:48:43